

CASE STUDY

Condition Monitoring



COMPANY

- GREGORY MINE SITE

CHALLENGE

- Diagnose cause of high damage recorded by MAX Watchdog System

LC PROVIDED

- Identified direct problem with hoist control
- Amended by mine site maintenance

